

MCHQD230 10-01A SGS Report No.:



INSPECTION REPORT

QINGDAO STARCO CHEMICAL CO.,LTD PRINCIPAL:

GOODS DESCRIPTION AS Urea PROVIDED BY CLIENT:

DECLARED QUANTITY: 1000 mt

INSPECTION LOCATION: Qingdao City, Shandong Province, China

INSPECTION DATE: January 16-17, 2023

SCOPE OF WORK: Visual Check Cargo Condition

Marking and Packing Checking

Sampling and Analysis

Container Cleanliness Checking

Container Stuffing Witness and Seal Stuffed Containers

VISUAL CARGO SURFACE CONDITION:

During sampling, the cargo was found to be white granules by visual checking as far as accessible and visible.

PACKING:

As far as accessible and visible, the cargo presented was packed in polypropylene plastic bags. Each bag was declared as 1000kgs net.

MARKING:

Marking was found to be printed and attached on the bags with declared Batch No. 20230115 during the inspection as far as accessible and visible, detailed photos please refer to below.





The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

the Company.

Unless otherwise agreed in writing, this document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cient's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention. To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443.

sting /inspection report & certificate, pleas

District, Qingdao, Sh 中国・山东・青岛市崂山区株洲路143号通标中心

www.sgsgroup.com.cn t (86-532) 68999888 sgs.china@sgs.com



SGS Report No.: MCHQD230(10-01A



SAMPLING:

Sampling method:	randomly sampling as per GB/T 6678-2003
Description of sampling:	30 bags from 1000 bags were randomly selected and opened for sampling purpose. Sample material was taken by one standard steel tube from each selected bag and all accumulated sample was finally mixed thoroughly and prepared into 2 sets of composite sample. One set of composite sample was sent to SGS Qingdao laboratory for required analysis and the other set of composite sample would be retained in SGS local office for 1 month for further reference if needed.
Note:	The testing results please refer to the testing report.

CONTAINER STUFFING WITNESS AND TALLY:

Process	Value	Remark
Before stuffing, the container(s) were visually checked by SGS	Yes	empty, clean and dry condition
During stuffing, the container(s) were under SGS's continuous witness	Yes	/
After stuffing, the container(s) were sealed by SGS	Yes	1-5-2-3-6-3-8

Per SGS Tally, total 1000 bags were loaded into 50 containers.

No.	Containe	r No.	SGS Sea	I No.	Shipping S	eal No.	Tally/ bags
1	CAIU24	42	KC167	71	ML-CN1	106	20
2	MRKU7	172	KC16	2	ML-CN0	877	20
3	MRKU7	926	KC122	3	ML-CN0	553	20
4	MRKU7	897	KC16	3	ML-CN1	114	20
5	MRKU7	924	KC16	4	ML-CN(882	20
6	MRKU8	416	KC16	5	ML-CN1	123	20



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

Unless otherwise agreed in writing, this document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-75) 8307 1443.

SGS Center, No.143, Zhuzhou Road, Lacehan District, Qingdao, Shandong, China 中国・山东・青岛市崂山区株洲路143号通标中心

t (86-532) 68999888 www.sgsgroup.com.cn t (86-532) 68999888 sgs.china@sgs.com



SGS Report No.: MCHQD230 10-01A

-53		_C				-	
7	MRKL	3933	KC1	'86	ML-CN01	- 55	20
8	MSKL	5420	KC1	'87	ML-CN18	36	20
9	MSKL	5250	KC1	'88	ML-CN02	38	20
10	MSKL	7618	KC1	'89	ML-CN18	34	20
11	MSKL	1194	KC1	'90	ML-CN01	62	20
12	MSKL	3856	KC1	'91	ML-CN02	11	20
13	MSKL	1445	KC1	'92	ML-CN18	13	20
14	MSKL	5823	KC1	'93	ML-CN01	83	20
15	MSKL	1702	KC1	'94	ML-CN01	54	20
16	MSKL	0670	KC1	'95	ML-CN18	29	20
17	SUDL	9252	KC1	['] 96	ML-CN01	56	20
18	SUDL	3835	KC1	'97	ML-CN18	39	20
19	TCKU	2920	KC1	['] 98	ML-CN01	74	20
20	TTNU	9680	KC1	'99	ML-CN01	85	20
21	FCIU	710	KC1	250	ML-CN01	26	20
22	HASL	3909	KC1	248	ML-CN01	07	20
23	MRKL	7045	KC1	251	ML-CN01	47	20
24	MRKL	9375	KC1	245	ML-CN01	17	20
25	MRKL	9478	KC1	300	ML-CN18	53	20
26	MRKL	3008	KC1	246	ML-CN01	27	20
27	MRKL	2878	KC1	243	ML-CN01	12	20
28	MRKL	1207	KC1	280	ML-CN01	41	20
29	MRKL	0660	KC1	277	ML-CN01	24	20
30	MRKL	1769	KC1	278	ML-CN01	20	20
31	MRKL	3629	KC1	271	ML-CN18	12	20
32	MRKL	9800	KC1	256	ML-CN01	35	20
33	MRSL	2366	KC1	255	ML-CN18	58	20
34	MSKL	5486	KC1	259	ML-CN01	89	20
35	MSKL	1693	KC1	276	ML-CN18	14	20
36	MSKL	2730	KC1	270	ML-CN01	46	20
37	MSKL	9474	KC1	252	ML-CN18	85	20
38	MSKL	3286	KC1	254	ML-CN01	37	20
39	MSKL	3029	KC1	272	ML-CN01	27	20
40	MSKL	5950	KC1	260	ML-CN02	07	20
41	MSKL	0568	KC1	241	ML-CN02	37	20
42	MSKL	204	KC1	242	ML-CN01	50	20



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

Unless otherwise agreed in writing, this document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing inspection report & certificate, please contact us at telephone: (86-75) 8307 1443.

testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443,

SGS Center, No.143, Zhuzhou Road, Lacehan District, Clingdao, Shandong, China 中国・山东・青岛市崂山区株洲路143号通标中心

t (86-532) 68999888 www.sgsgroup.com.cn

t (86-532) 68999888 sgs.china@sgs.com Member of the SGS Group (SGS SA)



MCHQD2300110-01A SGS Report No.:

43	MSKU	134	KC1	.79	ML-CN01	948	20
44	SUDU	936	KC1	:58	ML-CN01	947	20
45	SUDU	423	KC1	:53	ML-CN01	'38	20
46	SUDU	182	KC1	49	ML-CN01	318	20
47	SUDU	663	KC1	275	ML-CN01	949	20
48	TCLU	711	KC1	74	ML-CN01	936	20
49	TCLU	789	KC1	:57	ML-CN01	336	20
50	TEMU	576	KC1	:44	ML-CN01	711	20

Weather condition during inspection:

January 16~17, 2023

Fine

Any holder of this document is advised that information contained hereon is limited to the visual examination of the safely and readily accessible portions of the consignment only. Due to the nature of the cargo and limited access during inspection, items not recorded in the above description may be present.

This certificate does not release, nor certify the said vessel, containers, or materials as being "grain / organic / soil /

As per the instruction from the principal, SGS conducted the inspection for nominated cargo, without performing vessel loading or discharging supervision. Therefore, the contents of this report/certificate only reflects our findings at the time and place of inspection, and does not refer to any cargo that was shipped from or will be received at any port.

The sole function of any seals applied by SGS is to indicate that the material bearing such seals has been inspected by SGS. Seals applied by SGS are not intended to secure material, lock the container of such material, or otherwise provide any security function. SGS does not provide security services and disclaims any liability in this respect.

******Inspection Report End*******

Authorized Signatory

Jan 19, 2023

SGS-CSTC Standards Technical Services (Qingdao) Co., Ltd.



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

Unless otherwise agreed in writing, this document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein ere the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

testing /inspection report & certificate, please

中国・山东・青岛市崂山区株洲路143号通标中心

t (86-532) 68999888 t (86-532) 68999888

www.sgsgroup.com.cn sgs.china@sgs.com



Lab Reference No.:MNT230486QD

SGS Report No.:MCHQD2300110-01A

Testing Report Page: 1 / 2

TESTING REPORT

Principal Name: QINGDAO STARCO CHEMICAL CO.,LTD

Principal Address:

Declared Sample Name: Urea

Sample Received Date: 2023-01-19

Sample Testing Period: 2023-01-19 ~ 2023-01-29

Declared Sample Number:

Sample Condition on Receipt: Particle(2kg)

In accordance with instructions received from applicant, we prepared and carried out required test on the sample. The analysis results reported as refer to the next page(s)

SGS-CSTC Standards Technical Services(Qingdao) Co.,Ltd

RC Can

Authorised Signatory 2023-01-29



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company. Unless otherwise stated the results shown in this test report refer only to the sample(s) fested.

Unless otherwise agreed in writing, this document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

ng /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443

SGS Center, No.143, Zhuzhou Road, Laoshan District, Qingdao, Shandong, China 中国・山东・青岛市崂山区株洲路143号通标中心

t (86-0532) 68999367

www.sgsgroup.com.cn sgs.china@sgs.com



Lab Reference No.:MNT230486QD

SGS Report No.:MCHQD2300110-01A

Testing Report Page: 2 / 2

3 5 6	3 Sp. 5	Result	c c5 c6	
Test Items	Unit	6 15 6	Standard No.	
Urea content	%	98.9	ISO 5315-1984(E)	
Biuret	%	0.63	ISO 22241-2:2019(E)	
Aldehyde(as HCHO)	mg/kg	2.9	ISO 22241-2:2019(E)	
Alkalinity(as NH₃)	%	0.012	ISO 22241-2:2019(E)	
Phosphate(as PO ₄)	mg/kg	<0.5	ISO 22241-2:2019(E)	
Insoluble Matter	mg/kg	7.4	ISO 22241-2:2019(E)	
Ni	mg/kg	<0.2	ISO 22241-2:2019(E)	
Mg	mg/kg	<0.5	ISO 22241-2:2019(E)	
Zn	mg/kg	<0.2	ISO 22241-2:2019(E)	
Cr	mg/kg	<0.2	ISO 22241-2:2019(E)	
Al	mg/kg	<0.5	ISO 22241-2:2019(E)	
Cu	mg/kg	<0.2	ISO 22241-2:2019(E)	
Fe	mg/kg	<0.5	ISO 22241-2:2019(E)	
K S	mg/kg	<0.5	ISO 22241-2:2019(E)	
Na	mg/kg	<0.5	ISO 22241-2:2019(E)	
Ca	mg/kg	<0.5	ISO 22241-2:2019(E)	

*****The end****



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Unless otherwise agreed in writing, this document is aissued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Center, No.143, Zhuzhou Road, Laoshan District, Qingdao, Shandong, China 中国・山东・青岛市崂山区株洲路143号通标中心

t (86-0532) 68999367 t (86-0532) 68999367

www.sgsgroup.com.cn sgs.china@sgs.com